

From: [Phillip Winsor](#)
To: [Gary Moore/R6/USEPA/US@EPA](#)
Subject: Re: Falcon Refinery
Date: 06/06/2011 08:02 AM

Gary;

Regarding the Org. Chart, the TCEQ would be connected directly to the EPA only. Where and how you want to display it is up to you. I have spoken with Rafael recently regarding Falcon and understand the roles.

For the Region PM contact Terry Andrews in our Houston Region Office at 713/767-3560. He manages our superfund matrix PMs including the ones in Corpus Christi. He can connect you with a Corpus region PM. I have cc'd him on this response to give him a heads up.

Thanks for the update, and please keep me posted on the removal activities. I guess we'll see who ends up doing the RI/FS.

Phillip Winsor, PE
Superfund Section
Remediation Division
TCEQ
ph: (512)239-1054
fax: (512)239-2216
e-mail: pwinsor@tceq.state.tx.us

>>> <Moore.Gary@epamail.epa.gov> 6/3/2011 5:42 PM >>>
Philip:

At the present, EPA is planning on finishing up on the RI/FS. The RP has a meeting with our Division Director around June 29 to discuss whether EPA is going to allow them to complete the RI/FS work.

The RI/FS work is managed by the EPA RPM, Raphael Casanova. The Removal Action is being overseen by the EPA OSC which is me. How does TCEQ want to be incorporated into the org chart for the Removal Action and the RI/F?. Who would you like for me to coordinate with at the Corpus Christi Regional Office on our activities?

Thanks

Gary Moore
Federal On-Scene Coordinator
EPA Region 6
Cell: 214-789-1627
Work: 214-665-6609
email: moore.gary@epa.gov

From: "Phillip Winsor" <Phillip.Winsor@tceq.texas.gov>
To: Gary Moore/R6/USEPA/US@EPA
Date: 06/03/2011 03:45 PM
Subject: Re: Falcon Refinery

Thanks Gary;

I reviewed your e-mail and monthly report. I really don't have any comments about TRC's proposal to move wastes/rainwater, however, I would appreciate either you or TRC contacting our TCEQ Region Office prior to on-site activities such as this. I was



9567474

wondering if TRC was conducting the RI/FS or EPA. The monthly report didn't make that clear and also noticed the Org. Chart doesn't have any reference to the TCEQ.

Please keep me posted on activities conducted at the site, thanks.

Phillip Winsor, PE
Superfund Section
Remediation Division
TCEQ
ph: (512)239-1054
fax: (512)239-2216
e-mail: pwinsor@tceq.state.tx.us

>>> <Moore.Gary@epamail.epa.gov> 6/1/2011 2:25 PM >>>
Philip:

Please see the last update. I get reports on a monthly basis. I apologize that you have not been previously included on these updates. I will make sure that you get them when I receive them. Let me know if you have any questions.

Gary Moore
Federal On-Scene Coordinator
EPA Region 6
Cell: 214-789-1627
Work: 214-665-6609
email: moore.gary@epa.gov